		_							
_	Туре	л· #	Hits	Search Text	DBS	Time Stamp	Comme	Error	Erro
	BRS	L-1	15823	(power voltage) adj (network\$1 bus\$3)	US-PGPUB;	2006/05/18 09:16	•		
8	BRS	L2	1392	<pre>l same (micro\$1chip\$1 ic ics ((micro micro\$1electronic\$1) adj chip\$1) (integrated adj circuit\$2))</pre>	US-PGPUB;	2006/05/18			
m	BRS	L3	671	<pre>1 near10 (micro\$1chip\$1 ic ics ((micro micro\$1electronic\$1) adj chip\$1) (integrated adj circuit\$2))</pre>	US-PGPUB; USPAT	2006/05/18			
4	BRS	L5	18	3 and 4	US-PGPUB; Z	2006/05/18 09:19			
Ŋ	BRS	L4	57	2 same ((transmit\$4 receiv\$3 transceiver\$1 communicat\$4) near (data signal\$1))	US-PGPUB; USPAT	2006/05/18			
v	BRS	L6	45	4 not (lesesky and alan).in.	US-PGPUB; USPAT	2006/05/18 09:21			
7	BRS	1.7	<u>o</u>	3 same ((transmit\$4 receiv\$3 transceiver\$1 communicat\$4) near (data signal\$1))	US-PGPUB; USPAT	2006/05/18 09:30			
ω	BRS	L8	212	3 and ((transmit\$4 receiv\$3 transceiver\$1 communicat\$4) near (data signal\$1))	US-PGPUB; Z	2006/05/18 09:30			
6	BRS	L9	1177	l same ((transmit\$4 receiv\$3 transceiver\$1 communicat\$4) near (data signal\$1))	US-PGPUB; USPAT	2006/05/18 09:30			
10	BRS	L10	29	3 and 9	US-PGPUB; 2	2006/05/18 09:34			
11	BRS	111	26	9 10	US-PGPUB; Z	2006/05/18			